


+7 lights T5 Wiring Diagram PBR 1000L, v2015

around-->



- Parts: 4x T5HO Bulb 2,700K (P1090)
 3x T5HO Bulb 10,000 K (P1011)
 7x T5HO Ballast (P1016)
 1x 24" jumper cable (P1013)
 4x 26" jumper cables

**alternate bulb colour
 for 77" and 44": use 18" long round end connector
 for 26": cut power cord or (P1013) @ 18" with round connector, use 3/8" heatshrink
 18AWG ButtSplice on 8" square sided connector cut from (P1014)

